Scope of	Work for Property Lo	cated at	:	<u>4953</u>	North 19th Street	
Date:	Property is: Single Far 9/9/2015	mily 🗹	Duplex		Other 🗆	
ake no respo		after the in	spection da	te, or for	ity of Milwaukee, the Redevelopment Automissions through error or oversight. The Grant or HOME programs.	
Exterior	Condition Report					
Location Site	Required Work Landscaping	n/a 🗌	Yes 🗸	Note/ Self He	Comments elp	\$ Cost 300.00
	Steps/Handrails	n/a ✓	Yes 🗌			\$
	Service walks	n/a ☑	Yes 🗌			\$
	Fencing	n/a 🗌	Yes 🗸			\$ 200.00
	Parking	n/a ☑	Yes 🗌			\$
	Retaining walls	n/a ✓	Yes 🗌			\$
	Other	n/a 🗌	Yes 🗌			\$ 
	Other	n/a □	Yes 🗌			\$ 
Garage	Singles: repair	n/a 🗌	Yes 🗌			\$
	Shingles: Roof over existing	n/a 🗌	Yes 🗌			\$
	Shingles:Tear off & re-roof	n/a 🗌	Yes 🗌			\$
	Gutters/downspouts	n/a	Yes 🗌			\$
	Flashing	n/a 🗌	Yes 🗌			\$
	Eaves	n/a 🗌	Yes 🗌			\$
	Siding	n/a	Yes 🗌			\$
	Doors	n/a	Yes 🗌			\$
	Windows	n/a 🗌	Yes 🗌			\$
	Slab	n/a	Yes 🗌			\$
	Paint	n/a	Yes 🗌			\$
	Electrical	n/a	Yes 🗌			\$
Db	Other	n/a	Yes 🗸	Raze (	settled foundation) or repairs	\$ 3,500.00
Porches	Roof	n/a ✓	Yes 🗌			\$
	Deck-upper	n/a ☑	Yes 🗌			\$
	Decklower	n/a ☑	Yes 🗌			\$
	Steps/handrails	n/a ☑	Yes 🗌			\$
	Ceiling	n/a ☑	Yes 🗌			\$
	Guardrails	n/a 🗌	Yes 🗸			\$ 300.00
	Structural	n/a ☑	Yes 🗌			\$ 
	Paint	n/a 🗌	Yes ✓			\$ 300.00

n/a 🗌 Yes 🗌

Other

\$

## House

Chimney	n/a ☐ Yes ✓	\$ 500.00
Shingles: repair	n/a ☑ Yes □	\$
Shingles: Roof over existing	n/a ☑ Yes 🗌	\$
Shingles:Tear off & re-roof	n/a ☐ Yes ☑	\$ 8,700.00
Gutters/downspouts	n/a ☐ Yes ✓	\$ 250.00
Flashing	n/a ✓ Yes 🗌	\$
Eaves	n/a ☐ Yes ☑	\$ 200.00
Siding	n/a ☐ Yes ☑	\$ 150.00
Storm Doors	n/a ☐ Yes ✓	\$ 600.00
Prime ("main") Doors	n/a ✓ Yes 🗌	\$
Storm Windows	n/a ☐ Yes ☑	\$ 200.00
Prime ("main") Windows	n/a ☑ Yes 🗌	\$
Paint	n/a ☑ Yes □	\$
Foundation	n/a ☑ Yes 🗌	\$
Electrical	n/a ☑ Yes □	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$
Other	n/a 🗌 Yes 🗌	\$

Exterior: Estimated Cost:\* \$ 15,200.00

 $<sup>\</sup>mbox{\ensuremath{^{\star}}}\mbox{average contracted cost.}$  Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report						
	Unit: Entire unit (single family)	<b>✓</b>				Lower unit of duplex	
Mechanical Heating	Upper unit of duplex Required Work					Other $\square$	
	Repair/replace boiler	n/a	<b>V</b>	Yes			\$ 
	Repair radiation	n/a	<b>V</b>	Yes			\$
	Repair/replace furnace	n/a	V	Yes			\$
	Repair ductwork	n/a	<b>V</b>	Yes			\$
	Replace thermostat	n/a	7	Yes			\$
	Repair/replace grilles	n/a	V	Yes			\$
Electrical	Tune boiler/furn. insp ht exchang	n/a		Yes	<b>V</b>		\$ 350.00
Electrical	Repair/replace receptacles	n/a	<b>V</b>	Yes			\$ 
	Repair/replace switches	n/a	V	Yes			\$
	Repair/replace fixtures	n/a		Yes	<b>V</b>		\$ 100.00
	Install outlets and circuits	n/a	<b>V</b>	Yes			\$
	Install outlets and circuits	n/a	<b>V</b>	Yes			\$
	Install outlets and circuits	n/a	7	Yes			\$
	Install outlets and circuits	n/a	<b>V</b>	Yes			\$
	Upgrade service	n/a	<b>V</b>	Yes			\$
	Other	n/a		Yes			\$
	Other	n/a		Yes			\$
Plumbing	Repair/replace kitchen sink	n/a	<b>V</b>	Yes			\$
	Repair/replace kitchen sink fauce	n/a	V	Yes			\$
	Repair/replace tub	n/a	<b>V</b>	Yes			\$
	Repair/replace tub faucet	n/a	V	Yes			\$
	Repair/replace toilet	n/a	<b>V</b>	Yes			\$
	Repair/replace lavatory	n/a	V	Yes			\$
	Repair/replace lavatory faucet	n/a	<b>✓</b>	Yes			\$
	Repair/replace wash tub	n/a	<b>V</b>	Yes			\$ 
	Repair/replace wash tub faucet	n/a	<b>V</b>	Yes			\$
	Unclog piping:	n/a	<b>&gt;</b>	Yes			\$ 
	Repair drain/waste/vent piping	n/a	<b>✓</b>	Yes			\$
	Repair water piping	n/a	<b>V</b>	Yes			\$
	Repair/replace water heater	n/a	<b>V</b>	Yes			\$
	Other	n/a		Yes	<b>V</b>	Kitchen sink base cabinet bottom	\$ 100.00

n/a 🗌 Yes 🗸 Tub surround

Other

500.00

\$

Windows								
	Replace broken glass	n/a	<b>V</b>	Yes			\$	
	Repair or replace sash	n/a	<b>V</b>	Yes			\$	
Doors								
	Repair or replace doors	n/a	<b>✓</b>	Yes			\$	
	Repair or repl. locks/latches	n/a		Yes	<b>✓</b>	Self Help	\$	60.00
Walls/Ceiling	-							
	Repair or repl. @ defective	n/a		Yes	J		\$	600.00
Paint								
	Repair or repl. @ defective	n/a		Yes	J		\$	1,200.00
Fire Safety								
	Install smoke/CO alarm:bsmt.	n/a		Yes	<b>V</b>	Self Help	\$	60.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	<b>V</b>	Self Help	\$	60.00
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	<b>V</b>	Self Help	\$	60.00
Handrails	Repair/replace defective	n/a		Yes	<b>7</b>	Self Help	\$	375.00
Stairs	· · ·					·		
	Repair defective	n/a		Yes	V		\$	375.00
Floors	Repair defective	n/a		Yes	7		\$	1,200.00
Other	repair delective	11/4		100	<u> </u>		Ψ	1,200.00
		n/a		Yes	<b>V</b>	Hardpipe dryer	\$	125.00
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
						Interior: Estimated Cost:	\$	5,165.00
						Total Exterior and Interior Cost:*	\$	20,365.00
						* Office of the second of the		,

Inspected by: Mark Stack Date: 9/9/2015

## Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

 $<sup>\</sup>ensuremath{^{\star}}\xspace$  average contracted cost. Actual costs may vary. Self help will reduce the amount.